



SWI9X15C 5.0 PRI

Customer Release Notes

Document number	4116615
Rev	R01.00
Date	2014/11/07

Document History

Rev XX.YY	Date YYYY/MM/DD	Updates	Author
01.00	2014/11/07	Creation	KW

Table of Contents

1	INTRODUCTION	5
1.1	SCOPE OF THIS DOCUMENT	5
1.2	AUDIENCE OF THIS DOCUMENT	5
2	ABBREVIATIONS AND DEFINITIONS	5
3	RELATED DOCUMENTATION	5
4	NORTH AMERICA	6
4.1	AT&T 9902196	6
4.1.1	MC7355/EM7355	6
4.1.2	MC7354	6
4.2	GENERIC 9902574	6
4.2.1	MC7355/EM7355	6
4.2.2	MC7354	6
4.3	ROGERS 9902907	6
4.3.1	MC7355/EM7355	6
4.3.2	MC7354	7
4.4	SPRINT 9902350	7
4.4.1	MC7355/EM7355/MC7354/MC7350	7
4.5	TELUS 9902845	7
4.5.1	MC7355/EM7355	7
4.5.2	MC7354	7
4.6	VERIZON 9902266	7
4.6.1	MC7355/EM7355/MC7354/MC7350	7
5	EUROPE	8
5.1	GENERIC 9902338	8
5.1.1	MC8805/EM8805	8
5.2	GENERIC 9902674	8
5.2.1	MC7305/EM7305	8
5.2.2	MC7304	8
5.3	ORANGE 9903272	8
5.3.1	MC7305/EM7305	8
5.4	SWISSCOM 9903383	8
5.4.1	EM7305/MC7305	8

5.5	TELEFONICA 9902580	9
5.5.1	MC8805/EM8805	9
5.6	VODAFONE 9903271	9
5.6.1	EM7305/MC7305	9
6	ASIA PACIFIC	10
6.1	NTT DoCoMo	10
6.1.1	MC7330/EM7330	10
6.2	TELSTRA 9902509	10
6.2.1	MC7305/EM7305	10
6.2.2	MC7304	10

1 Introduction

1.1 Scope of this document

This document describes changes in the SWI9X15C 5.0 line of configuration files.

1.2 Audience of this document

These release notes may be distributed to all direct and indirect customers.

2 Abbreviations and definitions

Abbreviation/Acronym	Definitions
FDT	Firmware Download Tool
MBIM	Mobile Broadband Interface Model
PRI	Product Release Instructions
PRL	Preferred Roaming List
USIM	Universal Subscriber Identity Module

3 Related documentation

Ref. #	Doc. #	Document title
[R-1]	4115982	MC73xx-SWI9X15C_05-FW-CRN

4 North America

4.1 AT&T 9902196

4.1.1 MC7355/EM7355

Configuration	ID	Comments
005.008_001	16771	Preserve custom profiles across upgrade
005.008_000	n/a	Initial Release with SWI9X15C_05.05.16.00

4.1.2 MC7354

Configuration	ID	Comments
005.010_002	16771	Preserve custom profiles across upgrade
005.010_001	n/a	Initial Release with SWI9X15C_05.05.16.02

4.2 Generic 9902574

4.2.1 MC7355/EM7355

Configuration	ID	Comments
005.007_004	16639	Updated various settings to align with PTCRB PICS
	16877	Fix issue where UE cannot reliably camp on 1X/DO networks after switching from Sprint PRI to Generic PRI
005.007_002	n/a	Initial Release with SWI9X15C_05.05.16.00

4.2.2 MC7354

Configuration	ID	Comments
005.007_011	16909	Fix issue where UE cannot reliably camp on 1X/DO networks after switching from Sprint PRI to Generic PRI
	16639	Updated various settings to align with PTCRB PICS
005.007_001	n/a	Initial Release with SWI9X15C_05.05.16.02

4.3 Rogers 9902907

4.3.1 MC7355/EM7355

Configuration	ID	Comments
005.005_001	n/a	Initial Release with SWI9X15C_05.05.16.00

4.3.2 MC7354

Configuration	ID	Comments
005.005_010	n/a	Initial Release with SWI9X15C_05.05.16.02

4.4 Sprint 9902350

4.4.1 MC7355/EM7355/MC7354/MC7350

Configuration	ID	Comments
005.018_004	16482	Update to Sprint PRL file 51102 Update APN Class of activation profile to properly indicate to MBIM interface that it does not provide internet connectivity
005.018_003	n/a	Initial Release with SWI9X15C_05.05.37.00

4.5 Telus 9902845

4.5.1 MC7355/EM7355

Configuration	ID	Comments
005.006_001	n/a	Initial Release with SWI9X15C_05.05.16.00

4.5.2 MC7354

Configuration	ID	Comments
005.006_010	n/a	Initial Release with SWI9X15C_05.05.16.02

4.6 Verizon 9902266

4.6.1 MC7355/EM7355/MC7354/MC7350

Configuration	ID	Comments
005.013_014	16877	Fix issue where UE cannot reliably camp on 1X/DO networks after switching from Sprint PRI to Verizon PRI
005.013_013	15229	Update firmware to SWI9X15C_05.05.16.03
	15438	Preserve Shared Secret Data on upgrade to avoid the need from the UE to do an SSD Update the next time it connects to the 1X network
	14341	Resolve FDT Error 84 when upgrading while Verizon SIM inserted
005.013_010	n/a	Initial Release with SWI9X15C_05.05.16.02

5 Europe

5.1 Generic 9902338

5.1.1 MC8805/EM8805

Configuration	ID	Comments
005.006_000	n/a	Initial Release with SWI9X15C_05.05.16.00

5.2 Generic 9902674

5.2.1 MC7305/EM7305

Configuration	ID	Comments
005.006_000	n/a	Initial Release with SWI9X15C_05.05.16.00

5.2.2 MC7304

Configuration	ID	Comments
005.006_001	n/a	Initial Release with SWI9X15C_05.05.16.02

5.3 Orange 9903272

5.3.1 MC7305/EM7305

Configuration	ID	Comments
005.007_001	n/a	Initial Release with SWI9X15C_05.05.35.00

5.4 Swisscom 9903383

5.4.1 EM7305/MC7305

Configuration	ID	Comments
005.002_002	16899	Remove unnecessary CDMA parameters which are intermittently causing image switch failures
005.002_001	15490	Update Network Name format over MBIM interface
005.002_000	n/a	Initial Release with SWI9X15C_05.05.30.00

5.5 Telefonica 9902580

5.5.1 MC8805/EM8805

Configuration	ID	Comments
005.006_000	n/a	Initial Release with SWI9X15C_05.05.16.00

5.6 Vodafone 9903271

5.6.1 EM7305/MC7305

Configuration	ID	Comments
005.010_001	15912	Do not reject voice calls
	15544	Update Vodafone AU APN to Vodafone Live!
005.010_000	n/a	Initial Release with SWI9X15C_05.05.39.02

6 Asia Pacific

6.1 NTT DoCoMo

6.1.1 MC7330/EM7330

Configuration	ID	Comments
005.010_000	n/a	Initial Release with SWI9X15C_05.05.26.00

6.2 Telstra 9902509

6.2.1 MC7305/EM7305

Configuration	ID	Comments
005.006_000	n/a	Initial Release with SWI9X15C_05.05.16.00

6.2.2 MC7304

Configuration	ID	Comments
005.009_001	16221	Update firmware to SWI9X15C_05.05.26.02
005.008_000	n/a	Initial Release with SWI9X15C_05.05.26.00